




Tools needed (not supplied)



A		10x40	x45
B		7x50	x8
C		7x60	x4
D		D35	x4
E		M6x75	x6
F		M6x10x13	x6
G		6,3x70	x1
H		55x12,2x5	x4
J		4,2x35	x9

K		5x38	x1
L		3,5x40	x26
M		D4x13	x8
N		D8x13	x2
P		D10x15	x5
R		D15x18	x7
S		GLUE	x1
T		4mm	x1



①



②




4mm



C		7x60	x4
---	---	------	----









4mm

 $2 \times$ 


D		D35	x4
---	---	-----	----

4





E		M6x75	x6
F		M6x10x13	x6
R		D15x18x3	x6


5 LADDER LEFT




LADDER RIGHT



ASSEMBLING LADDER  
LEFT SIDE








ASSEMBLING LADDER  
RIGHT SIDE



B		7x50	x8
M		D4x13	x8


6



G		6,3,x70	x1
R		D15x18	x1

H		55x12,2x5	x4
K		5x38	x1
N		D8x13	x5
P		D10x15	x2

7



8

