



# ASSEMBLY INSTRUCTION GA/GAO - 4.6 BED - UK


## PARTS LIST

| NO | DRAWING                                                                           | DESCRIPTION  | QTY |
|----|-----------------------------------------------------------------------------------|--------------|-----|
| ①  |  | HEAD BOARD   | 1   |
| ②  |  | FOOT BOARD   | 1   |
| ③  |  | SIDE RAILS   | 2   |
| ④  |  | MIDDLE RAIL  | 1   |
| ⑤  |  | SUPPORT RAIL | 3   |
| ⑥  |  | SLAT FRAME   | 12  |


## HARDWARE LIST

| NO | DRAWING                                                                             | DESCRIPTION    | QTY |
|----|-------------------------------------------------------------------------------------|----------------|-----|
| A  |  | BOLT M8 x 15   | 8   |
| B  |  | SPANNER        | 1   |
| C  |  | BOLT M6 x 40   | 6   |
| D  |  | ALLEN KEY      | 1   |
| E  |  | SCREWS M4 x 30 | 14  |


## STEP 1




## STEP 2




## STEP 3



STEP 4



STEP 5



STEP 6

