


BRAFDLSON Bramwell Folding Corner Desk

ASSEMBLY INSTRUCTIONS

Thank you for purchasing the BRAFDLSON Bramwell Folding Corner Desk.
Please read the instructions carefully to ensure safe operation of the product.



Size: 1200 x 425/725 x H765 mm


Colour: SONOMA OAK

PLEASE READ this sheet prior to assembly to familiarise yourself with the various stages of construction.

Carefully open the pack supplied and check the contents against the parts and fittings check list. Do not destroy any of the packaging until you are certain that you have all the necessary parts for the assembly.

CAUTION: There are small components used in the construction of this unit. These loose items should be kept away from young children whilst assembling your unit to avoid the danger of choking hazards.

Tools Required



(NOT INCLUDED)



1 Person Build



30 MINS
Set Up

BRAFDLSON Bramwell Folding Corner Desk

ASSEMBLY INSTRUCTIONS

**IMPORTANT - READ CAREFULLY - RETAIN THESE INSTRUCTIONS
FOR FUTURE REFERENCE.**

INFORMATION

- This product is intended for a maximum weight of 30 kg. Do not exceed this weight.
- Due to the size of this product we recommend that it is assembled in the room intended for use.
- When you are ready to start, make sure that you have plenty of space and a clean, dry area for assembly.
- Unwrap all packaging materials and place the components on top of the carton box or on a clean floor to prevent it from scratching.
- Ensure that this product is fully assembled as illustrated before use.
- Check all screws or bolts are tightened and inspect regularly.
- This product should only be used on firm, level ground.
- Make sure the legs remain in contact with the ground.
- Tools not required.

INFORMATION

- DO NOT use this product if parts are missing,damaged or worn.
- DO NOT sit or stand on the desk.


CARE INFORMATION

- Never use scourers, abrasives or chemical cleaners.
- To clean wipe with a sponge and warm soapy water. Do not use solvent based cleaners or detergents as they can bleach or damage the product.
- Do Not place hot items directly onto the desk surface always use a heat resistant mat.

BRAFDLSON Bramwell Folding Corner Desk

ASSEMBLY INSTRUCTIONS





Please check the pack contents before assembling this product. If any components are missing, please contact your retailer. The fittings pack contains small items that should be kept away from small children.



BRAFDLSON Bramwell Folding Corner Desk


ASSEMBLY INSTRUCTIONS

PARTS

A 	B 
DESCRIPTION: TOP PANEL QTY:1 PC DIMENSION: 1200x95x15MM	DESCRIPTION: SHELF PANEL QTY:2 PCS DIMENSION: 591x240x15MM
C 	D 
DESCRIPTION: TOP PANEL QTY:1PC DIMENSION: 1200x630x15MM	DESCRIPTION: METAL FRAME QTY: 1PC


FIXINGS (TO SCALE)

Ref	Dimensions	Qty
c	SCREW (4X14mm)	18
d	SCREW (4X16mm)	6
e	BOLT (6x40mm)	2
g	BOLT (6x30mm)	1



FIXINGS (NOT TO SCALE)

a	HINGE	3
b	PLASTIC PLATE	3
f	ALLEN KEY	1



CAUTION: There are many small components used in the construction of this product. Please keep these components away from young children whilst assembling this product.


If you keep the fittings in a bowl during assembly you will be less likely to lose them!

BRAFDLSON Bramwell Folding Corner Desk



ASSEMBLY INSTRUCTIONS

Layout Parts on Soft Surface

Layout all part on a soft surface i.e. Rug,carpet or packaging carton





X2



BRAFDLSON Bramwell Folding Corner Desk


ASSEMBLY INSTRUCTIONS

STEP 1	PARTS REQUIRED
	A: TOP PANEL X1 C: TOP PANEL X1 a: HINGE X3 b: PLASTIC PLATE X3 c: SCREW X12 d: SCREW X6

STEP 2	PARTS REQUIRED
	B: SHELF PANEL X2 D: METAL FRAME X1 c: SCREW X6

BRAFDLSON Bramwell Folding Corner Desk


ASSEMBLY INSTRUCTIONS

STEP 3	PARTS REQUIRED
	e:BOLT X2 g:BOLT X1 f:ALLEN KEY x1

BRAFDLSON Bramwell Folding Corner Desk

ASSEMBLY INSTRUCTIONS


FOLDING STEPS



BRAFDLSON Bramwell Folding Corner Desk

ASSEMBLY INSTRUCTIONS

Complete Assembly



Keep instructions for future reference

